EXHIBIT U





Construc	tion Deficie	ncy Rep	ort			CD No.	: 312E1-037	
i		NY	C Department o	of Environmenta	al Protection			
	-		WM-11 Croton	Water Treatme	nt Plant			
Contract No.:	CRO-312E1							
Contractor:	Schlesinger-Siemens Electrical, LLC							
Building Location:	Various Locations	Equipme Type and No.;		Drawing No	Drawing No/Spec. Section:		Spec. 16131	
Schlesinger Sier	Deficiency: Use onens Electrical LL	C (SSE) is u	ising WALSALL (conduit couplings	in various location	ns. This product	is has not been	
specifications sh	e Engineer for app hall be submitted f	oroval nor i	s the manufacture oval of the Engin	er/vendor been ap eer"or equal" ma	proved. Specifical iterials are to be a	tion 16131 states	that, "material Engineer."	
·								
Reported By:		Name: Hoo	shang Sharif	Signature:	IN A	Date:	5/27/2010	
Approved By:		Name: Steve	e l-fammel	Signature:	112 U	Date:	5/27/2010	
Disposition:	Repair		X Replace		ngineer res-Design Input	Accept	As Is Scrap	
	ails: Schlesinger S nit the WALSALL			is to replace the W	ALSALL conduit	couplings with	an approved	
					Expected Compl	etion Date:	6/11/2010	
QA Review of Disposition:	N	ame: Mel	V. Garafalo	Signature: M	. Shrofelo	Date: ç	127/10	
Disposition Verification of Contractor's Repai by Inspector:	r Ni	ıme:	Western Committee of the Committee of th	Signature:		Date:		
Deputy Resident Engineer's Approval:	Na	me:		Signature:		Date:		